## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s): Perkins	<b>Date(s):</b> 9-Jul-20
Company/Owner: Intermountain Gas Company	Unit/OPID: 8160
company content	0100
Inspection Type & Time (1 day) To	tal Inspection Days: 1
Standard: Construction: 1 Training: (T)(D) Integrity Managen  M/M: Follow-up: OQ: Damage Prevention	
Inspection Summary	
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.	
Observed a Das-co crew boring 300', line locating, trenching/shore box and welding at 1155 Caldwell Blvd, Caldwell, Idaho. All procedures were followed. Typed up report  Areas observed during this project were: Excavating, line locating, welding, pot holing and boring.  Attachments:  IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project.  OQ's for all observed employees are located in file for the project.	
Yes No X	by (date):
Inspector (Lead):  Bruce Perkins	<b>Date:</b> 7/9/2020
Reviewer:	Date:
Darrin Ulmer	Date.